TOP SECRET



IMAN D

PHOTOGRAPHIC INTELLIGENCE REPORT

CHERNOVTSY ARMY BARRACKS
ROSHTSHINSKAYA AL 2, USSR
(CARPATHIAN MILITARY DISTRICT)
DECLASS REVIEW BY NIMA / Dod

handle via TALENT-KEYHOLE control only

TOP SECRET

Nandle Via TALENT-KEYNOLE Control System Only

# TOP SECRET CHESS RUFF

TCS 12605/65 CIA/PIR-67061

CIA IMAGERY ANALYSIS DIVISION

CHERNOVISY ARMY BARRACKS ROSHISHINSKAYA AL 2, USSR

(48 17N-025 55E)

(CARPATHIAN MILITARY DISTRICT)

Handle Via TALENT-KEYHOLE Control System Only Handle Via TALENT-KEYNOLE Control System Only

## TOP SECRET CHESS RUFF

TCS 12605/65 CIA/PIR-67061

#### CIA IMAGERY ANALYSIS DIVISION

The following alphabetical designators are used to delineate functional areas within military installations.

- A. Billeting area
- B. Vehicle storage/maintenance
- C. General storage area
- D. Ammunition storage
- E. Miscellaneous (hospitals, prisons, POL, personnel training facilities and unidentified facilities)
- F. Small arms range
- G. Driver training area
- H. Support
- J. Tank/assault gun range
- K. Flat trajectory range
- L. Subcaliber range
- M. APC range
- N. Combined arms range
- P. Artillery training area
- Q. Infantry training area
- R. Special or unidentified area

#### NOTE:

- 1. The absence of one or more alphabetical designators indicates that those functional areas were not observed at that particular installation.
  - 2. Lower case leters (i.e., Ba) are used to delineate more than one area of a particular functional category.
- 3. Numbers are used with the alphabetical designators in some instances to identify vehicles or groups of vehicles within a functional area (i.e., Ba 1).

Ur

Handle Via TALENT-KEYHOLE Control System Only

## TOP SECRET CHESS RUFF

TCS 12605/65 CIA/PIR-67061

CHA IMAGERY ANALYSIS DIVISION

25X1D

## CHERNOVISY ARMY BARRACKS ROSHTSHINSKAYA AL 2, USSR

#### FUNCTIONAL AREAS

- A. 1 Multistory barracks
  - 2 Barracks
  - 1 Barracks/administration building
  - 8 Support buildings
- B. 1 Vehicle/equipment storage building
  - 2 Vehicle/equipment storage building
  - 2 Vehicle/equipment storage buildings
  - 1 Probable maintenance building (monitor roof)
  - 1 Building under construction
  - 3 Support buildings
- D. 2 Revetted explosives storage buildings

#### VEHICLES/PIECES OF EQUIPMENT

Three possible trucks are located by the probable maintenance building.

### OCCUPANCY ALD ACTIVITY


The only snow observed on roofs is on the north side of three of the storage buildings. Heavy vehicular scarring is observed in the motor pool area with distinct scarring observed on both sides of the east vehicle/equipment storage shed. The barracks area has all sidewalks and foot paths cleared of snow.

#### PI REMARKS

The installation is covered on clear, fair quality photography. No security measures separating the barracks area from the motor pool can be observed.

All measurements have been made by the CIA/IAD project analyst. They should not be construed as being mensuration data compiled by the NPIC Technical Intelligence Division.

**3** -



Mandle Via TALENT-KEYNOLE Control System Only

# TOP SECRET CHESS RUFF

TCS 12605/65 CIA/PIR-67061

CIA IMAGERY ANALYSIS DIVISION

REFERENCES

PHOTOGRAPHY

MISSION

DATE

PASS

FRAME

CLASSIFICATION

25X1D

MAPS AND CHARTS

U.S. Air Target Chart, Series 200, Sheet 0233-21HL, Second Edition, August 1962 (SECRET)

25X1D

DOCUMENTS o

SPIR-20-58, Areas of Military Interest, Chernovtsy, USSR, 12 June 1958 (TOP SECRET CHESS)

Army. PIB-TK-8-63, Military Installation - Chernovtsy, USSR, 6 February 1963 (TOP SECRET CHESS RUFF)

REQUIREMENT

CIA. C-RR5-82,756

CIA/IAD PROJECT

30063-6